بنام خدا لیست تجهیزات دوزیمتری و کنترل کیفی آزمایشگاه گروه تصویربرداری پزشکی دانشکده پیراپزشکی ارومیه

Devices	Company
1. The Piranha Premium System With	RT1 سوئد
QAB/MAS-2	
به همرا کامپیوتر دستی ونرم افزار	
Is based on a Pirhana model657for R/F and mammography	
Included external probes : Pirnaha Dose Probe For Input dose to image intensifiers,	
Scattered and leakage radiation,	
Piranha Light Probe For measurements on monitors and for measurement of ambient light,	
Piranha CT slice probe - CT- SD16 for CT dose	
measurements, Piranha Mas-2 for non-invasive mA and mAs	
Firallia Was-2 for non-invasive ma and mas	
2. Densonorm 21 (ECO)	Pehamed آلمان
دانسیتومتروسنسیتومتر (مرکب)	
21-step sensitometer and densitometer With measurement	
integrated in one unit.	
FOR X- Ray constancy testing.	4501
3. Dose Area Product Meter 006682DAP W3	Pehamed آلمان
Rectangular, transparent ionization chamber with	
electronic and double-line	
Display(inc. adapter with accessory holder)	(47 D.1 1
4. ALPHA Test-Phantom(DIN6868/3+4)	Pehamed آلمان
فانتوم رادیولوژی - فلوروسکوپی	
For constancy testing Of X-Ray Direct radiography and	
fluoroscopic per German standard	

5. DSA-Test Phantom(DIN 6868/8)For Constancy Testing Of Digital Subtraction Angiography System ,per German Standard	Pehamed آثمان
فانتوم آنژیوگرافی	
Digital subtraction Angiography system, per German Standard	
6. Dental Phantom Per(DIN 6868/5)	Pehamed آلمان
فانتوم دندان	
For quality- control Of X-Ray unit per German Standard.	
7. Aluminum Step Wedge (11 Step)	Pehamed آلمان
For determine Of sensitometric curve shape, speed and mid gradient Of X-Ray screen film System For medical radiography.	
8. Cassette Test Grid (per DIN 6832/2)	Pehamed آلمان
ابزار تست گرید For testing cassette film-screen contact.	
9. Check-Plate For Cassettes	Pehamed آلمان
ابزار تست کاست To check The Uniformity Of The Intensifying factor of X-Ray	
10. Basic Unit ,Alpha Plus, For Constancy	Pehamed آلمان
Testing Of X-Ray Dose	
دزیمتر استاندارد به همراه پروب های با قابلیت های مختلف	
Dosimeter with LCD, serial interface and plug-in for	
different Detectors. For the constancy test of all analog and digital Y Pay	
For the constancy test of all analog and digital X-Ray techniques.	
Dose Detector in the Absorption filter	

11. Euro-Phantom "MAMMO"	ا آلمان Pehamed
فانتوم ماموگرافی	
For monitoring the technical parameters mammography	
Imaging system per the requirements of the European	
guidelines Quality Assurance In Mammography.	
12.011007 Cassette Test Grid Mammo	Pehamed آلمان
ایزار تست گرید - ماموگرافی	
Very fine-mesh test gride (size 27 cm*32 cm)to test the	
film screen contact of mammography cassettes.	
13.011006 Aluminum Step Wedge (21 Step)	Pehamed آلمان
For exposure of 21 density steps on the mammography	
film.	
14. Calibrate able Digital Thermometer	Pehamed آلمان
ترمومتر برای تست تاریکخانه	
A highly accurate thermometer to check temperature	
during service Proof protective cover, wall/belt holder,	
battery	
Measurement range : - 50+230C,	
15. Basic Unit For Light Intensity	Pehamed آلمان
Measurements	
دستگاه سنجش شدت نور- لوکسیمتر	
Hand hold ,light intensity measurement device with LCD	
Display, serial interface and plug-in.	
For different light- detectors.	
Designed for the acceptance testing and constancy testing.	
16.ID-Printer "US"	Pehamed آلمان
10:12 11mtc1 C5	
درج کننده مشخصات روی فیلم	